

ROUTING							
то	: NAME	AND ADDRESS	10	DATE	INITIALS		
1							
2							
3							
4							
	ACTION	DIRECT REPLY	T	PREPA	RE REPLY		
	APPROVAL	DISPATCH			MENDATION		
	COMMENT	FILE		RETURN			
	CONCURRENCE	INFORMATION		SIGNATURE			
REMARKS:							
FROM: NAME, ADDRESS, AND PHONE NO.							
L							

	SECRET	62
	(Security Classification)	•
		25X1
	(See inside cover)	
CONTROL	NO. <u>Z-15388/83</u>	
COPY	NPIC/PEG (10/83) OF	_

Warning Notice
Intelligence Sources or Methods Involved

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

.

SECRET

(Security Classification)

## Warning Notice Intelligence Sources or Methods Involved (WNINTEL) or (D)

## NATIONAL SECURITY INFORMATION Unauthorized Disclosure Subject to Criminal Sanctions

## DISSEMINATION CONTROL ABBREVIATIONS

NOFORN-

Not Releasable to Foreign Nationals

NOCONTRACT-

Not Releasable to Contractors or

Contractor/Consultants

PROPIN-

Caution-Proprietary Information Involved

ORCON-

Dissemination and Extraction of Information

Controlled by Originator

REL . . .

This Information has been Authorized for

Release to ...

Sanitized Copy Approved for Release 2011/03/29: CIA-RDP91T00712R000200360011-1 SECRET 25X1 (c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER Page  $\frac{1}{}$  of  $\frac{1}{}$ Z-15388/83 Attachment to NPIC/PFG (10/83) Copy\_\_\_\_ ARRIVAL OF SERVICE GANTRY COMPONENTS TYURATAM SPACE LAUNCH SITE Al, USSR 25X1 1. SIGNIFICANCE: SEPVICE GANTRY REPLACEMENT COMPONENTS HAVE BEEN DELIVERED TO THIS DAMAGED AND INOPERATIVE LAUNCH SITE SINCE 25X1 (SWN) 2. REMARKS: THREE STABILIZER ARMS AND SEVERAL UNIDENTIFIED ARCH-SHAPED PIFCES OF FOUIPMENT ARE ON THE APRON. STABILIZER ARMS PROBABLY WERE DELIVERED FROM TVIIRATAM SDACE 25X1 LAUNCH SITE B1 SERVICE CANTRY COMPONENTS ARE BEING STOFFD AT LAUNCH SITE BI AWAITING REFURBISHMENT OF THAT LAUNCH SITE. A FOURTH STABILIZER ARM IS EXPECTED TO BE DELIVERED TO SITE A1. PARTIALLY DISMANTLED SERVICE ARM, FEMOVED FROM THE DAMAGED LAUNCH PAD IS ALSO ON THE AFRON WHILE A SECOND 25X1 SERVICE ARM REMAINS IN PLACE ON THE LAUNCH PAD. THE RAPID PACE OF THE ONCOING REFAIR EFFORT INDICATES THE IMPORTANCE THE SOVIETS APE PLACING ON THEIR ATTEMPT TO HAVE THIS SITE OPERATIONAL AS SOON AS POSSIBLE. 25X1 3. COORDINATES 45-55-12N 063-20-33E 25X1 These notes have been prepared for briefing purposes only and should not be used for detailed ana-25X1 lytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. WARNING NOTICE Intelligence Sources and Methods Involved SECRET

Sanitized Copy Approved for Release 2011/03/29 : CIA-RDP91T00712R000200360011-1

25X1